

DPF/FAP/CAT filter REGENERATION/CLEANING

Warranty: [x]12 months []6 months []none

Date of service: 2017-09-05

Customer name: test

Vehicle make and model: Audi a5

Vehicle odometer: 220000

Filter No: test

Warranty coverage : 1. removal of ash and soot deposits plogging filter channels of over 90 % 2. maintaining the integrity of the core (monolith) of the filter during cleaning

Cleaning report:

1. Initial inspection

Filter assessment: [5] [x] [3] [2] [1]

2. Pressure measurement: before [240] after [8] mbar

3. Cleaning of the catalyst : [x] Yes [] No

4. Prevailing type of deposits : [] oil [x] soot [] ashes [] colour


Recommendations: driver adaptation

place for a stamp and signature

DPF/FAP/CAT filter REGENERATION/CLEANING




PRESSURE DIAGRAM
Pressure drop by 96.67%



BEFORE AFTER
PRESSURE DIAGRAM

Pressure drop by 232.00 mbar

PHOTOS BEFORE:



PHOTOS AFTER:











place for a stamp and signature